



INSTALLATION AND MAINTENANCE INSTRUCTIONS SIGHT GLASSES

(SW12 - DW12 - DW12G - DW16SS - DW40)

GENERAL

- 1. These instructions must be carefully read before any work involving products supplied by VALSTEAM ADCA ENGINEERING S.A. is undertaken.
- 2. The installation procedure is a critical stage in a life of a sight glass and care should be taken to avoid damage of the equipment.

Warning!

- -Do not touch the equipment without appropriate protection during working operation because it may conduct heat if the used fluid is at high temperature.
- -Before starting maintenance be sure that the equipment is not pressurized or hot.
- -Avoid spraying of hot sight glass with cold fluid, or failure could result.
- -The equipments must be used within the working temperature and pressure limits laid down for them, otherwise they may fail (refer to nameplate and/or IS Information Sheet).
- -For temperatures over 300 °C you must protect glasses with lamellae of mica.
- -Replace borosilicate glasses when are exposed to temperature superior to 280 °C for a total of 300h.
- -Do not remove the nameplate attached to the equipment. Serial number and other useful information is stamped on it.

INSTALLATION

- 1. Before to install remove plastic covers placed on flanges or connection ends. The equipment has an arrow or Inlet/Outlet designations. Be sure that it will be installed on the appropriate direction.
- 2. The SW and DW sight glasses can be installed in any position on the outlet side of a steam trap.
- 3. Open slowly the upstream interception valve to avoid water hammer.

MAINTENANCE

- 1. The ADCA sigh glasses do not require any particular maintenance. Cleaning or changing of the glass may become necessary from time to time. The cleaning intervals depend on the degree of contamination of the fluid. Examine the glass to ascertain the extend of any damage or service wear.
- 2. When reassembling makes sure that all gasket faces are clean and always use a new gasket. Tighten cover bolts uniformly in a diagonal sequence.
- 3. For further information refer to the relevant IS (Information Sheet) or consult our Sales Office.

RATINGS:

Sight Glass	PN
SW12	16
DW12	16
DW12G	16
DW16SS	16
DW40	40









Window Material	Borosilicate Glass	Tempered Glass		
Max. Operating Temp.	300 °C	120 °C		
Min. Operating Temp.	-10 °C	-10 °C		

CE Marking:

This product have been designed for use on water and steam which are in Group 2 of the European Pressure Equipment Directive 97/23/EC and it comply with those requirements. The product carries the CE mark when falling in category 1 and above.

GROUP 2 (STEAM and WATER)				
MODEL	SIZES	CATEGORY		
SW12	DN 15-25	SEP		
DW12	DN 32-50	SEP		
DW12G	DN 15-50	SEP		
DW12G	DN 65-150	1		
DW16SS	DN 15-25	SEP		
DW40	DN 15-25	SEP		
DVV40	DN 32-50	1		

PARTS LIST FOR SIGHT GLASS:

CODE	DESIGNATION	MODEL	SIZE DN	POS.NR.	QTY.
A.96.5100.015	Borosilicate glass & gaskets	SW12-DW16SS	1/2"-1"	3, 4	1 set
A.96.5150.032	Tempered glass & gaskets	DW12-DW12G	11/4"- 11/2"	3, 4	1 set
A.96.5150.050	Tempered glass & gaskets	DW12-DW12G	2"	3, 4	1 set
A.96.5150.015	Tempered glass & gaskets	DW12G	15 - 25	3, 4	1 set
A.96.5150.032	Tempered glass & gaskets	DW12G	32 - 40	3, 4	1 set
A.96.5150.050	Tempered glass & gaskets	DW12G	50	3, 4	1 set
A.96.5150.065	Tempered glass & gaskets	DW12G	65 - 80	3, 4	1 set
A.96.5150.100	Tempered glass & gaskets	DW12G	100	3, 4	1 set
A.96.5150.125	Tempered glass & gaskets	DW12G	125	3, 4	1 set
A.96.5150.150	Tempered glass & gaskets	DW12G	150	3, 4	1 set
A.96.7100.015	Borosilicate glass & gaskets	DW40	1/2"-3/4"	3, 4	1 set
A.96.7100.025	Borosilicate glass & gaskets	DW40	1"	3, 4	1 set
A.96.7100.032	Borosilicate glass & gaskets	DW40	11/4"-11/2"	3, 4	1 set
A.96.7100.050	Borosilicate glass & gaskets	DW40	2"	3, 4	1 set















Recommended tightening torques:


Model	POS.NR.	SIZE DN	Nm
SW12	2	1/2"-1"	60 - 65
DW12	5	11/4"	25
DW12	5	11/2"-2"	40
DW12G	5	15 - 20	12
DW12G	5	25 - 32	25
DW12G	5	40 - 50	40
DW12G	5	65 - 100	45
DW12G	5	125 -150	55
DW16SS	2	1/2"-1"	60-65
DW40	2	1/2"-1"	110±5
DVV40	5	11/4"-2"	40














DW16SS

DW40 - DN 1/2"-1"

DW40 - DN11/4"-2"

LOSS OF GUARANTEE: Total or partial disregard of above instructions involves loss of any right to guarantee.





